



SV06 Extruder Cable Support



AllTheHobbies

[VIEW IN BROWSER](#)

updated 12. 2. 2023 | published 12. 2. 2023

Summary

For Saggy Cable

[3D Printers](#) > [Accessories](#)

Tags: [extruder](#) [cable](#) [support](#) [sovol](#) [cablesupport](#) [sv06](#)
[sovolsv06](#) [sv06sovol](#)

Extruder cable support for the Sovol SV06 to prevent sagging and contact with your prints. Turn off power. Remove extruder cable. Place support over the cable keeper hooks. Reattach extruder cable.

Model files

[extruder-cable-support-part-1.stl](#)

License

This work is licensed under a
Creative Commons (4.0 International License)



Attribution-NonCommercial

- ✗ | Sharing without ATTRIBUTION
- ✓ | Remix Culture allowed
- ✗ | Commercial Use
- ✗ | Free Cultural Works
- ✗ | Meets Open Definition